

PUMA 4100/5100 series

Date	Corrections				Corrections Reason
	Page	Contents	AS-IS	TO-BE	
2015-09-30		Version	150923SU	150930SU	
	6p	Turret > 2-axis model - No. of tool stations	10ea (std.) / 12ea 12ea (std.) / 10ea	12ea (std.) / 10ea 10ea (std.) / 12ea	Error change
2015-10-28		Version	150930SU	151028SU	
	8p	Standard / Optional Specifications > TAILSTOCK	Programmable type / Live Center / Built-in dead center	Manual type / Programmable type / Live Center / Built-in dead center	Add Item